

Czech Sport Aircraft, a.s.	SERVICE BULLETIN	Czech Sport Aircraft, a.s. Na Záhonech 1177/212, 686 04 Kunovice Czech Republic office@czechsportaircraft.com
No. SB-SC-002		Rev.: -
Date: 2010/09/23		
Page: 1 of 2		Date: -

MODEL AFFECTED:	SportCruiser / PiperSport
SUBJECT:	Issue of POH Supplement No 3
AIRCRAFT AFFECTED:	All SportCruiser aircraft produced All PiperSport aircraft produced Aircraft serial numbers S/N P1001060 and subsequent will have the subject of this bulletin accomplished in appropriated chapters of POH.
COMPLIANCE:	Within 25 flight hours but not later than 30 October 2010.

DESCRIPTION:

Service Bulletin concerns issue of POH Supplement No 3.
There were several cases in operation, when due to unlatched canopy the canopy opened during flight. Information in this Supplement completes or replaces information in the basic Pilot's Operating Handbook concerning to unlatched canopy.

APPROVAL:

Engineering design aspects of this SB are Czech Sport Aircraft a.s. approved.

AUTHORISATION TO PERFORM:

Pilot / Owner

MANPOWER:

Approximately 10 minutes is required to complete this Service Bulletin.
Man-hours are based on hands-on time, and may vary with personnel and facilities available.

REFERENCES:

SPORTCRUISER POH
PIPERSPORT POH

PUBLICATIONS AFFECTED:

SPORTCRUISER POH
PIPERSPORT POH

ACCOMPLISHMENT INSTRUCTIONS:

1. Download appropriate POH Supplement No 3 from
<http://www.czechsportaircraft.com/technical-publications/>

POH Supplement No 3_1 is valid to S/N:

06SC008, 06SC020, 06SC041, 07SC014, 07SC015, 07SC016, 07SC017, 07SC019, 07SC020, 07SC021, 07SC022, 07SC026, 07SC027, 07SC028, 07SC029, 07SC031, 07SC033, 07SC034, 07SC035, 07SC036, 07SC038, 07SC039, 07SC040, 07SC041, 07SC043, 07SC044, 07SC045, 07SC046, 07SC050, 07SC051, 07SC054, 07SC056, 07SC059, 07SC061, 07SC062, 07SC063, 07SC067, 07SC068, 07SC071, 07SC074, 07SC075, 07SC076, 07SC078, 07SC081

Czech Sport Aircraft, a.s.	SERVICE BULLETIN	Czech Sport Aircraft, a.s. Na Záhonech 1177/212, 686 04 Kunovice Czech Republic office@czechsportaircraft.com
No. SB-SC-002		Rev.: -
Date: 2010/09/23		
Page: 2 of 2		Date: -

POH Supplement No 3_2 is valid to S/N:

06SC037, 06SC03807SC018, 07SC024, 07SC025, 07SC032, 07SC042, 07SC047, 07SC052, 07SC053, 07SC055, 07SC060, 07SC064, 07SC065, 07SC066, 07SC069, 07SC070, 07SC077, 07SC079, 07SC082, 07SC083, 07SC084, 07SC085, 07SC086, 07SC090, 07SC091, 08SC087, 08SC088, 08SC089, 08SC093, 08SC094, 08SC098, 08SC099, 08SC100, 08SC101, 08SC102, 08SC104, 08SC105, 08SC106, 08SC109, 08SC110, 08SC111, 08SC112, 08SC115, 08SC117, 08SC121, 08SC125, 08SC126, 08SC129, 08SC132, 08SC133, 08SC134, 08SC135, 08SC136, 08SC139, 08SC140, 08SC142, 08SC143, 08SC144, 08SC149, 08SC150, 08SC155, 08SC156, 08SC157, 08SC158, 08SC159, 08SC167, 08SC168, 08SC169, 08SC172, 08SC173, 08SC176, 08SC179, 08SC185, 08SC189, 08SC190, 08SC193, 08SC194, 08SC195, 08SC199, 08SC200, 08SC203, 08SC204, 08SC207, 08SC208, 08SC211, 08SC212, 08SC215, 08SC218, 08SC219, 08SC223, 08SC224, 08SC225, 08SC228, 08SC229, 08SC231, 08SC232, 08SC237, 08SC238, 08SC241, 08SC242, 08SC243, 08SC244, 09SC165, 09SC166, 09SC246, 09SC247, 09SC248, 09SC249, 09SC252, 09SC254, 09SC257, 09SC258, 09SC262, 09SC263, 09SC264, 09SC265, 09SC266, 09SC267, 09SC268, 09SC270, 09SC273, 09SC275, 09SC276, 09SC277, 09SC278, 09SC279, 09SC280, 09SC281, 09SC282, 09SC283, 09SC284, 09SC285, 09SC286, 09SC287, 09SC288, 09SC294

POH Supplement No 3_3 is valid to S/N:

09SC274, 09SC289, 09SC291, 09SC295, 09SC302, 09SC304, 09SC308

POH Supplement No 3_4 is valid to S/N:

09SC290, 09SC293, 09SC296, 09SC298, 09SC300, 09SC301, 09SC303, 09SC305, 09SC309, 09SC311, 09SC321, 09SC322, 09SC323, 09SC324, 09SC326, 09SC327, 09SC329, 10SC297

POH Supplement No 3_5 is valid to S/N:

10SC290, P1001001, P1001002, P1001003, P1001004, P1001005, P1001006, P1001007, P1001008, P1001009, P1001010, P1001011, P1001012, P1001013, P1001014, P1001015, P1001016, P1001017, P1001018, P1001019, P1001020, P1001021, P1001022, P1001023, P1001024, P1001025, P1001026, P1001027, P1001028, P1001029, P1001030, P1001031, P1001032, P1001033, P1001034, P1001035, P1001036, P1001037, P1001038, P1001039, P1001040, P1001041, P1001042, P1001043, P1001044, P1001045, P1001046, P1001047, P1001048, P1001049, P1001050, P1001051, P1001052, P1001053, P1001054, P1001055, P1001056, P1001057, P1001058, P1001059

2. Print downloaded page.
3. Insert appropriate POH Supplement No 3 behind the current last page of POH.
4. Update aircraft records to reflect compliance with this SB.