

Czech Sport Aircraft, a.s.	<b>SERVICE BULLETIN</b>	Czech Sport Aircraft, a.s. Na Záhonech 1177/212, 686 04 Kunovice Czech Republic office@czechsportaircraft.com
No. SB-SC-003		Rev.: -
Date: 2010/10/15		
Page: 1 of 1		Date: -

<b>MODEL AFFECTED:</b>	PiperSport
<b>SUBJECT:</b>	Issue of POH Supplement No. 4
<b>AIRCRAFT AFFECTED:</b>	All PiperSport aircraft produced
<b>COMPLIANCE:</b>	Within 25 flight hours but not later than 31 November 2010.

**DESCRIPTION:**

The Service Bulletin concerns the issuance of POH Supplement No. 4.  
This supplement changes Service ceiling to Demonstrated service ceiling in chapter 2.7 of POH.

**AUTHORISATION TO PERFORM:**

Pilot / Owner

**MANPOWER:**

Approximately 10 minutes is required to complete this Service Bulletin.  
Man-hours are based on hands-on time, and may vary with personnel and facilities available.

**REFERENCES:**

PiperSport POH

**PUBLICATIONS AFFECTED:**


PiperSport POH

**ACCOMPLISHMENT INSTRUCTIONS:**




1. Download POH Supplement No. 4 from <http://www.czechsportaircraft.com/technical-publications/>
2. Print the downloaded page.
3. Insert POH Supplement No. 4 behind the current last page of the POH.
4. Update aircraft records to reflect the compliance with this SB.

**APPROVAL:**

This SB is prepared by:

<b>Title</b>	Design Organisation engineer
<b>Name</b>	Josef Glos
<b>Hand written signature</b>	

and approved by

<b>Title</b>	Compliance Verification Engineer	Head of the Design Organisation	Airworthiness Manager	EASA (if applicable)
<b>Name</b>	Tomáš Maršálek	Jiří Konečný	Josef Vlachynský	N/A
<b>Hand written signature</b>				N/A