

Czech Sport Aircraft a.s.	SERVICE BULLETIN	Czech Sport Aircraft a.s. Na Záhonech 1177/212, 686 04 Kunovice Czech Republic office@czechsportaircraft.com
No. SB-SC-012		Rev.: -
Date: 2011-11-30		
Page: 1 of 1		Date: -

MODEL AFFECTED:	PS-28 Cruiser / SportCruiser
SUBJECT:	Issue of the PS-28 Cruiser/SportCruiser Maintenance Manual, Revision 2 - CR-MM-1-0-00-R2
AIRCRAFT AFFECTED:	S/N P1102001, P1102004, P1102005, P1102006, P1102012, P1102013, P1102014, P1102015, P1102016, P1102017, P1102019, P1102022, P1102025, P1102027 and P1102050. For P1102002, P1102003, P1102007, P1102008, P1102009, P1102010, P1102011, P1102018, P1102020, P1102021, P1102023, P1102024, P1102026, and subsequent (except P1102050) this SB will be included to the MM by CSA prior to the aircraft shipment.
COMPLIANCE:	After receipt of this SB, but till December 31, 2011 at the latest.

DESCRIPTION:

The Service Bulletin concerns the issuance of the PS-28 Cruiser/SportCruiser Maintenance Manual Revision 2.

AUTHORISATION TO PERFORM:

Pilot / Owner

MANPOWER:

-

REFERENCES:

PS-28 Cruiser/SportCruiser Maintenance Manual (CR-MM-1-0-00).

PUBLICATIONS AFFECTED:

PS-28 Cruiser/SportCruiser Maintenance Manual (CR-MM-1-0-00).

ACCOMPLISHMENT INSTRUCTIONS:

1. Download the PS-28 Cruiser/SportCruiser Maintenance Manual, Revision 2 from <http://www.czechsportaircraft.com/technical-publications/>
2. Print the downloaded pages.
3. Insert pages of Revision 2 instead of current appropriate pages.
4. Update aircraft records to reflect compliance with this SB.

APPROVAL:

This SB was approved by:

Title	Head of the Design Organisation	Airworthiness Manager
Name	Jiří Konečný	Josef Vlachynský
Hand written signature		