

SUPPLEMENT No. 04

SERVICE CEILING

This Supplement must be attached to the Pilot's Operating Handbook during airplane operation.

Information in this Supplement completes or replaces information in the basic Pilot's Operating Handbook for the below mentioned parts only. Limitations, procedures and information not mentioned in this Supplement and included in the basic Pilot's Operating Handbook stay valid.

This Supplement completes information necessary for the airplane operation with equipment installed on the airplane.

2. LIMITATIONS

2.7 *Service ceiling*

Demonstrated service ceiling..... 10,000 [ft] (3,000[m]) |